

TAVOLA SELEZIONE
SCIOLINA

WAX SELECTION
CHART



NEVE NUOVA – I cristalli originali sono visibili
NEWS SNOW – The original crystals are visible

Freddo estremo Extreme cold	-25° C -13° F
Molto fredda Very cold	-20° C -4° F
Freddo Cold	-15° C 5° F
Fresco Cool	-10° C 14° F
Caldo Warm	-5° C -23° F
Umido Damp	0 C 32° F

BASE WAXES Humidity <70%	BASE WAXES Humidity >70%	FLUOR FREE WAXES	GRAPHITE
BB	BB	SX	CM
BB	BB	SX	CM
BB	BR	SX SM ES	CM
BR	BR	SM	C
BR	BT	SM	CF
BB	BT	SP	CF



NEVE IN TRASFORMAZIONE La neve non è mai scongelata,
però i cristalli non sono più visibili
TRANSFORMING SNOW The snow never melted but
original crystals are not visibles

Molto fredda Very cold	-20° C -4° F
Freddo Cold	-15° C 5° F
Fresco Cool	-10° C 14° F
Caldo Warm	-5° C -23° F
Umido Damp	0 C 32° F

BASE WAXES Humidity <70%	BASE WAXES Humidity >70%	FLUOR FREE WAXES	GRAPHITE
BB	BB	SX ES	CM
BB	BR	SX SM ES	CM
BR	BR	SM ES	C
BR	BT	SM ES	CF
BT	BT	SP	CF



NEVE TRASFORMATATA Ghiacciata, dura, compatta, bagnata, sporca
TRANSFORMED SNOW Icy, Hard, compact, slush, dirty

Molto fredda Very cold	-20° C -4° F
Freddo Cold	-15° C 5° F
Fresco Cool	-10° C 14° F
Caldo Warm	-5° C -23° F
Umido Damp	0 C 32° F

BASE WAXES Humidity <70%	BASE WAXES Humidity >70%	FLUOR FREE WAXES	GRAPHITE
BB	BB	SX ES	CM
BB	BB	SX SM ES	CM
BB	BR	SM ES	C
BR	BR	SM ES	CF
BT	BT	SP	CF

FLUORINATED
WAXES

ADDITIVES &
ACCELERATORS

BASE WAX
All temperatures

BASE Special
Working WAX
-2°C/-9°F | 28°F/16°F

	POWDER	CUBE		BA
LF	POWDER	CUBE		BA
MF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	BB	BA
MF	POWDER	CUBE	BB	BA

Freddo estremo Extreme cold
Molto fredda Very cold
Freddo Cold
Fresco Cool
Caldo Warm
Umido Damp

FLUORINATED
WAXES

ADDITIVES &
ACCELERATORS

BASE WAX
All temperatures

BASE Special
Working WAX
-2°C/-9°F | 28°F/16°F

	POWDER			BA
MF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	SPRAY	BA

Molto fredda Very cold
Freddo Cold
Fresco Cool
Caldo Warm
Umido Damp

FLUORINATED
WAXES

ADDITIVES &
ACCELERATORS

BASE WAX
All temperatures

BASE Special
Working WAX
-2°C/-9°F | 28°F/16°F

	POWDER	CUBE		BA
LF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	SPRAY	BA
MF	POWDER	CUBE	SPRAY	BA

Molto fredda Very cold
Freddo Cold
Fresco Cool
Caldo Warm
Umido Damp

WAX